Approved For Release 2003/01124 : 212 RDP74B00776R600100130035-8

	,		
ù	UCLW-0070		
05)/44	TO: Chief of Station, 1960	25X1A	
25X1A	FROM:		
	SUBJECT: Operation " Comments	25X1A	
	REFERENCE: WAQW-4130, (TS-155554), dated 18 November 1960, subject same as above		
	1. Reference paragraph 2. Air Rescue for ferry flights was provided solely because of request in On previous ferry flights there has never been any special SAR provided.	25X1A	
	2. Reference paragraph 3 a, b, c. Since this was an overt ODUNIT operation all coordination was through and by personnel who cooperated very well. As emphasized in telecon on 10 November 1960 ODUNIT said would be on station as requested but might have to vary on station position because of varying types	25X1 25X1A 25X1	
	of aircraft and operational procedures of SAR. In the same telecon it was clearly stated there was no way to infon coordination	25X1A	
25X1A	except by message from Headquarters. Hence,	25X1A	
	3. Reference paragraph 3 d. Info for briefing should have been given by SAR coordinator on 10 November 1960 if requested by in telecon with at SAR, San Francisco, California.	25X1A 25X1A	
	4. Reference paragraph 4. Headquarters received WECEN 6545 12/1123Z and it was passed to in 32 minutes, that is receipt was at 12/1155Z. We will continue to make every effort to get such	25X ₁ A	
	messages topromptly and whenever possible to transmit them early to allow additional time for flight planning.	25X1A	
	5. Reference paragraph 5. Paragraph 3 E, 13, and 14 of Operations Order 16-60 were meant to indicate that ferry missions from were unit planned and directed with the sole proviso that take off time in 3 E, 13 were met. The designator GF 60-X indicates as much. In the future, Operations Order will be more specific to eliminate any confusion.	25X1A	
25X1A [6. ODUNIT notified Headquarters of the arrival of the petachment at Hickam on the morning of 12 November 1960 at about 1430Z. The delay obviously was on this end and is something we must continually guard against. This is an inherent hazard in an operation coordinated through a second or third party and the only solution is to anticipate delays and plan alternative action.	25X1A	

Approved For Release 200001/24 CARDP74B00776R000100130038686 1 of 3

Approved For Refease 2003/01/24 : CIA-RDP74B00776R000100130035-8

m runways are closed, informa-	25X1A
	25X1A
	05\/4.4
	25X1A
,	d use Hickam runways. There- ou were correct in filing for indicated in the Pacific FLIP. ns to prevent this sort of

TS-155578 Page 2 of 2 Copy / of 5

Approved For Release 2003/01/24 : CIA-RDP74B00776R000100130035-8

	· IUF	OLUMPI - TO THE REAL PROPERTY OF THE PARTY O	
:		DISPATCH NUMBER WACH-4130	*** **********************************
		Copy 4 of 4 copies	
	TO: Headquarters FROM: Chief of Test Site	NOV 18 1360	25X1
	SUBJ: Operation Co	monts	
	1. In order to improve our operation on Operations Order 6-60,	on future exercises comments	25X1
	information.	are submitted for your	25X1
	2. Air Rescue was not provided for inferry flight.	n the Operations Order on the	
25X1A	3. Air Rescue coordination by ODUNIT and the Air Rescue unit.	created confusion between	
	a. The coordinates were changed i	rom those requested.	İ
25X1A	b. The location of the Alpha orbi		
	c. No information was received on	Eravo orbit.	
	d. Insufficient information was a detailed briefing of the crews on Air I calls were made.		25X1
25X1A	4. Winds were not received until 11552 late. This delay was caused for the mocommunication facilities at Mc Clellan between and Headquarters.	which was almost an hour est part by a break down of AFB, the relay station	
	a. This delay resulted in less time the Flight Planner to accomplish mission preparation of flight plans for two sor begin six hours prior to take off.	e available than desired for n planning requirements. The ties by one navigator should	
25X1A	b. communication facilities was made to obtain wind at take off mint time). On future operations the communications approximately seven hours before take of hour to establish contact and obtain wind the contact and obtain wind	cation facilities will open	
25X1A	5. The Operations Order made no mention from Headquarters to	nof pormal massages	25X1A
25X1A	70 Go no Go. Par 3A-6 of the Or		20/(1/

Copy 4 of 4 copies
1 TS Control # 155554

Approved For Release 2003/01/24 : CIA-RDP74B00776R000100130035-8

Approved For Release 2003/01/24 CIA-RDP74B00776R000100130035-8

		25X1A
	Headquarters CHALICE would notify hen Hickam Detachment was in place at Hickam and ready to retrieve	25X1A
	This notification had not arrived at take off minus two hours at which time a telephone call was made to verify that the Detachment was in place and ready to receive the	25X1A
25X1A	6. The Operations Order specified that the ferry route would be from to Hickam. Hickam is closed to all traffic and the landing base is Honolulu International. This is a very monor point but must be taken into consideration when filing the Flight Clearance Form, DD 175.	
		25X1A

Copy 4 of 4 copies
TS Control #15554

ZIPI	OTHER (Specify)	DATE /	TIME	. CLAS	ONFIDEA	T H'IAI
FROM:	BW CLINTON S	HERMAN_AFI	3 OKLA	CON	MUNICATIONS CENT	R ONLY:
2		AFB NEBR DALE AFB LA AFB OKLA TON SHER		OK/a,	* ** *	
	FOR					
CONF	IDENTIAL		/PR	emission,		(RE
1.	2af/kcsm/ <u>90</u>	PAREFS			DEPLOYME	ダナン
2. Г				101	*	
y .	21/1/200					
1	24 / 120		_Z			
4.	1 KC-135	.				•
5.	WRSPI	V				
6.	NIA			8		
7. T	7,		1.2	-hoa	5 Z. TWO HE	υ <i>(1</i> 2 -
· L	Marsuss		•			• '
	HOLDING	IN LIEL	SOFAI	LIERN	ATE. (WI	161
- / <u>:</u>					1	
8. 6	DUALIFIE	D. JAW	SACM S	5-12		
9. 1	PREMISSIO	N' REPO	RTFO	R REN	AINING LE	C-WILL
	BE SENT					
		-			PAGE	Of
WRITER				00	FICATION ATTEMENT	TOTA.
			MAJZ	ISHFUL	JINT HULL	HAI

25X1A

25X1A 25X1A

25X1A

25X1

25X1

25X1A

Approved For Release 2003/01/24: CIA-RDP74B00776R000100130035-8